

12 DEC 1935

Surveyors 11. 12. 35

Received from Chief Surveyors

NAME ^{3/5} Bulgarian

Report done

No. 162132

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

3rd No. 1 SURVEY PARTLY HELD.

12. 35 When proposed to be completed

Why held, &c.

Limit on aft crank web of HP crank shaft (to 22 or more) repair 12. 35

Submitted action be deferred for a short time pending a further communication

[Signature]
11. 12. 35

ack to Owners:— 14/12



© 2019

Lloyd's Register Foundation

W486-0225