

M.S. "SEMINOLE".

It is submitted the Belfast Surveyors be advised that the Owners² desire to take advantage of the fact that this vessel is now under survey for repairs at their Port, to have the vessel examined with a view to compliance with the requirements of the "International Convention respecting Deadlines", so as to avoid delay when regulations based on the Convention are introduced.


The Owners have obtained the following plans from the Builders :-

- (1) Engine and Boiler Room Casings
- (2) Poop and bridge bulkheads
- (3) Details of fore and aft gangway.

These plans should be sent to the Surveyors for their guidance.

They should examine the casings, hatchways, gangways, etc. fitted in the ship, and should compare them with the requirements contained in the Convention Report, copies of which have already been sent for their guidance, and report by letter in order that any alterations required may be intimated to the Owners. They should return the plans to this Office.

26/9/30.



26.9.30.



© 2020

Lloyd's Register
Foundation

W 48-0079