

Undertaking base

7 JUN 1935

Chief Surveyors 1. 6. 35

Received from Chief Surveyors

EL'S NAME *5/8 - Purley Oaks*

Report *Rot-*

No. 22293

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

Survey *2nd S.S. No 3*

When due *4.31*

SI due 6.32

SI due 6.31

note:- Another Special Survey due

The 2nd S. S. No.3 became due 4,31 and no part of the Survey has been held.

The vessel being laid up the Owners have furnished the usual undertaking.

The ship was generally examined ^{A FLOAT} in July 1933.

The case received further consideration in May 1934 (Special Survey 3 years overdue) when no general examination was required.

In reply to enquiry the Rotterdam Surveyors write that the vessel is still laid up.

Another Special Survey became due 4,35.

It is submitted for consideration whether the Owners should be asked to arrange for the ship to be again generally examined.

9/9

6.6.35



© 2020

Lloyd's Register Foundation

W488-0211