

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor 25 JAN 1923

VESSEL'S NAME *St Se RIVER TAFF*Rpt. *Eff*No. *46069*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

*1<sup>st</sup>* S.S. No. 2 AND DAMAGEDamage through *Grounding**(Jk 556) (NYK 24709)*

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....							
Removed and faired or repaired.....	4						
Faired or repaired in place.....	2	6					

Other items:-

*vessel placed on slipway, bottom cleaned Coated  
Belge Keels repaired and minor repairs effected*

The *1<sup>st</sup>* S.S. No. 2 has also been held and following repairs done  
due to wear and tear:-

*Hatches repaired and minor repairs effected**Cargo battens are <sup>now</sup> not fitted*

It is submitted the vessel is worthy to remain classed with record  
of Survey *1-26 Eff* and notation of *S.S. Eff No 2-26*  
as recommended.

*100 A.1**1-26 Eff**S.S. Eff No 2-26*

The Certificate of Classification to  
be endorsed "*Cargo battens not  
fitted*" and the same notation to be  
printed in the Register Book.

Insert



© 2021

Lloyd's Register  
Foundation

W489-0015