

COPY.

rs of Classification (which m
sely as in Register Book & Sup

CHARACTER.
Special Survey.

The class is Subject to the Star board donkey boiler (17016) not
being used until repaired & satisfactorily reported upon

5E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Koll

Rpt.

hph

No. 34151

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey

DAMAGE & WEAR AND TEAR.

The next Surveyors report repairs have now been effected to
Star board donkey boiler but recommend the furnaces
be again examined before end of 1.33.

They further recommend that the lower head on both
fuel oil heater be renewed before the end of 1.33.

It is submitted the vessel is eligible to remain as classed with
record of Survey Subject as recommended.

Without other Special Conditions

HRM
27.10.32

Continuous Survey not advanced.



© 2020

Lloyd's Register
Foundation