

If Surveyed Afloat or in Dry Dock

Afloat

Donkey Boilers

Report No. 102828 Port

COPY.

Particulars of Examination and Repairs (if any) Repair

Lloyd's Register of Shipping.



where the Surveyor has not made a special damage report he is required to state whether he

has or this purpose, and why they were declined

made by surveyor else? If so, by whom?

go inside each Main Boiler separately and make a thorough examination at this time?

Donkey Port

NEW YORK

State for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

MARCH 2nd, 1934.

Also what special notes, in the absence of internal examination, were adopted by the

Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they adjusted?

Did the Surveyor examine the Safety Valves of the Donkey Boiler?

To what pressure were they adjusted?

This is to Certify

that I have

Surveyed the Boiler and Machinery of the

M. V. "KOLL" 10044

tons gross register of Oslo

Has screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Is an approved distance fit

Has shaft now been changed?

If so, state reasons

Has the shaft been previously used?

Has it a continuous liner?

Is an approved distance fit

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

Recommended that the record of machinery remain as now

classed

be made in the Register Book in the case of this vessel.

General Observations, Opinion, and Recommendation:—The machinery of

Engineer Surveyor to Lloyd's Register.

is in one opinion, to remain as now classed with

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

Committee's Minute

10m.7.30.

expenses (if chargeable)

\$50.00

NEW YORK FEB 23 1934

W49-0060

TUE. 3 JUL 1934

er Survey

FOR W.H.

Lloyd's Register Foundation