

Chief Ship Surveyor 28-10-35

Received from Chief Ship Surveyor 31 001 1935

NAME "JAMAICA SETTLER" Rpt. Lon. No. 102116

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)


Survey


The 2nd S.S.No.3 became due 1,35 and a proposal to carry out same within the year of grace has been agreed to in view of a general examination made in August last.

The London Surveyors report that at the request of the Owners and with a view to the issue of an interim certificate a satisfactory general examination has been made of the vessel afloat including the examination of the windlass and steering gear and found satisfactory.

The vessel is proceeding to the River Clyde where it is stated she will be broken up.

It is submitted action be deferred and the Glasgow Surveyors requested to advise this Office when the work of demolition has commenced.


30-10-35
MAB



© 2020

Lloyd's Register
Foundation

W490-0231

RETAIN

726.3 on 1
TONNAGE:
GROSS 72
DER DE. 6
T 45
veyed Afte
B=CellDB
al capacity
N.B.—All alter
If the Vessel
e tanks examin
rs, and of the
st Rebo
odical Surveys,
use of Repairs,
account of Da
ed besides being
placement of A
e back of this
amage cases w
ffered his servi
Interin
AIRS, OR EX
I an
ent after
w done:
r, bu
ually
k vessel
RY OF DAMAGE
enewed ...
removed and Faired
aired or Repaired in
F CONDITION OF
of Decks ...
Fastenings ...
lating ...
in way of sideli
ts.
P
ames
als
m Plating...
Lloyd's Register
State clearly w
survey, thus, fo
ey, 1.24," or "to
his vessel
ch recon



© 2020

Lloyd's Register
Foundation