

W491-0094

22 APR 1938

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME

"CAMBAY STAR"

Rpt.

Bom.

No.

5697

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The class is subject to the wood mainmast being removed for repair or renewal on return to Bombay this month (3,38).

The Bombay Surveyor now reports the mast as above dealt with.


It is submitted the vessel appears worthy to remain as classed without record of survey, without special condition.

As now, Without etc.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

22/4/38
J.H.
[Signature]

In S.R.L. Bottom is slightly set up in way of No 2 D.B. (air)



Lloyd's Register
Foundation