

REPORT of SURVEY for REPAIRS, &c.

of writing Report. 22. 3. 1938

When handed in at Local Office. 22. 3. 1938

Port of *Bombay*in
book.Survey held at *Bombay*

Date, First Survey

*19-3-38*Last Survey *21-3-1938*on the *Wood, Iron or Steel**S.S. CAMBAY STAR*(No. of Visits *2*)

TONNAGE:-

GROSS *637*NET *431*DER. DK. *320*Built at *Lowestoft*

By whom

J. Chambers, Ltd.

When

YEAR

MONTH

*1920 11*Owners *Cambay State*

Owners' Address

(if not already recorded in Appendix to Register Book).

Managers *Port Development Com.*Port belonging to *Bombay*Surveyed Afloat or in Dry Dock? *Afloat*Name of Dock *Princis*

Destined Voyage

Cell D B or D Ba

feet; u & B

feet; f

feet

Capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

All alterations in the existing records should be underlined.
 The Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Report, No.

*5689*Port *Bom*

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.	For Special Survey.	Date of last survey and of Periodical Surveys.	Years Assigned for Survey.	Machinery and Boiler Surveys (including date of N.B., if any).
*100 A1	-1-37	5-38		*LMC 1-37
				*NB 5-31
				TS. CL 12-35
				BL 3-38
GASOL BATTERIES NOT FITTED.				
S.S. Lme. No. 3-9-32				
S.S. Bom. No. 1 -37				

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

RS, OR EXAMINATION AS PER RULE, FOR

Repairs to Mast

Please see also *Bombay Report No 5689.*

Mast removed to workshop - defective top of mast removed and new top mast scarped to lower portion.

At test load of 1.5 tons the working load was applied on completion of repairs and all found satisfactory

OF DAMAGE REPAIRS:-

Renewed

Removed and Faired or Repaired

Repaired or Repaired in place

CONDITION OF THE

Shell Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

(State which)

Rudder

Steering gear and its connections

Windlass

Have pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Air and Sounding Pipes

Dblng. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Oil Bunkers

Schippers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking

Treenails

Breasthooks & Stemson

Transoms Pointers, & Crutches

Timbers of Frame at openings

Ditto Ditto at other places

Stringers, Clamps & Shells

Salting

(State if examined.)

Copper, or Y.M. of Wood Vessels

(State if on Felt).

When put on, Month

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchor, No. of

Chain Locker

Cables (State if now ranged)

length (on board) mean diamr.

Rule length size

Hawser & Warps

Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 2, 4," or "to remain as classed and to have record of survey, 1, 2, 4, and the notations of ss No. 1-24 and ptND24, &c."

This vessel, so far as now seen, is in good condition and eligible, in my opinion, to remain as classed without fresh record of survey.

(per Section 20)

Repair Fee (if any)

Expenses (if chargeable)

Surveyor's Fee (if any)

Fees applied for,

22. 3. 1938

Received by me,

19.

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

TUE 26 APR 1938

Character Assigned

As now

Without Spl. Cond.

W491-0096

Lloyd's Register Foundation