

Has shaft now been changed?

If so, state reasons

Is an approved appliance fitted at the after end of  
ated?

Jan. 12, 32.

2 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

*Trader*

Rpt.

*hwc*

No.

*90372*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS FOR S.S.~~ No

This Survey, due

*4.33*

now

~~partly~~

held

now

completed, and the following repairs carried out (due to *mechan*) :-

*Hummer & Combustion Chamber repairs*  
*S.S. No 1 due 7.32. Postponement until Rpt (approved)*  
*Machinery generally examined & found in order*

It is submitted the vessel is eligible to remain as classed, with

notation of

*MD 8.33*

as recommended.

*W494-0049*

© 2020  
Lloyd's Register  
Foundation