

REPORT on the

S. S. "Trader"

Sld. Rpt. 30482 dated 17.10.20.

It is submitted the Sld. Surveyors be informed that it is observed from the above report that the freeboard marked on the vessel's sides is $6\frac{1}{2}$ inches. As the freeboard assigned by this Society is $8\frac{1}{2}$ inches it is concluded that their figure was given in error but they should confirm this.

W.S.

24.10.20

W 494 - 0065



© 2020

Lloyd's Register
Foundation