

Chief Surveyors 19.12.35

Received from Chief Surveyors

SHIP'S NAME *SSc "LOUGH FISHER"* Report *pls* No. *56445*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Survey *Damage* When due _____

Subject to shell plating in way of starboard side aft being dealt with at first convenient opportunity & to outer plates (E. 118-35) being specially examined at next dry docking.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

MB
pld
© 2020 20 35



Lloyd's Register Foundation

W494-0083