

W 494 - 0093

Surveyors _____

Received from Chief Surveyors _____

AME Steel S.S. "KINNAIRD HEAD"

Report *Two*

No. 82024

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

in cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

vey _____ When due _____

✠ 100 A.I. (Steel)

1 Dk (Steel) "Well Dk

FPT 44', APT 28'

FK, 3BH, Cew, Ply to A. CP. Q 86', B 9', F 24'


Richy aff

MD

21.3.21

See *Ch. 11* *Wine*
2.4.21

Concluded the thickness & riveting of the bulge plates, and the riveting
butts of the Raised Quarter Deck Side plating and for Castle Side plating
required but the Surveyors should state if this is so



Lloyd's Register
Foundation