

F.E.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel SS. "GUERNICA" Rpt. Bbo. No. 5587

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.

verse No. 71.81 Depth "d" 21.5
 ng: Table No. 3 Description Bulb angle as approved
 tudinal No. 23370
 Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{\quad}{\quad} = \frac{\quad}{\quad}$ 9.9

Ridge Deck Sheerstrake as approved.

The Anchors have not been tested nor the Stream Chain supplied.

This vessel appears to have been built in accordance with the
 and the approved plans, and it is submitted she is eligible to
 ased 100 A- (steel)

10k. (steel)

Cell DB 279' 743t. FPT 58t. APT 98t.

FK. 5BH. Cem. P28', B100', F45'.

M. AES
26.5.20



© 2019

Lloyd's Register
 Foundation

W497-0007