

BOARD REPORT on the

*Guernica*

It is submitted the Rpt C 12(b) be  
 returned to the Bilbao Surveyors and they  
 be requested to verify the position of the  
 summer load line for ordinary cargoes given  
 on their form as 1246 <sup>mm</sup> and which should  
 be 1264 <sup>mm</sup>, after which the Surveyors  
 should forward a new form to this office.

*L.B.*  
 2/4/36



© 2019

Lloyd's Register  
 W497-0019  
 Foundation