

Received by Chief Ship Surveyor

13/12/12

Received from Chief Ship Surveyor

VESSEL'S NAME

M.S. Australia

Rpt.

Horn No. 13072

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

94.54

Depth "d"

17.11 1/2

Framing: Table No.

2 page 7

Description

as approved

Longitudinal No.

45599

Proportions

Length =

11.98

Depth

Bridge Deck Sheerstrake 04 less than required but compensated by bulk angle frames to give equivalent strength.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100A-1 (Stub) as recommended.

\pm 100A-1 (Stub)

2nd (Stub) Lower Deck in No. 1 & 4 holds will date

W.B. bul D Ba 184 u 84 1886 + 191 1946 EPT 1206

FK 984 Cum Lloyd at GP P+B 372 F81

3297-0188

© 2019

Lloyd's Register
Foundation