

1

Sent to Chief Surveyors 24/5/11

Received from Chief Surveyors

VESSEL'S NAME Stl. S.S. "Elephanta" Report Gls No. 30159

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have at the salient points presented in the endorsement." --Extract from Sub-Committee's Report, 24/5/12.)

Nature of Survey 1st Entry When due

RETAIN

✱ 100 AI ("Steel") "Shade deck"
2 Dks. (v Stl-w.s.) & Shade deck (Stl-Leak s.)
WB= cell DBa 85' v E+B 100' f 151' 748t. F.P.T. 39 A.P.T. 312.
FK "7BH., 5 BH. to Upper Dk., 2 BH. to Second Dk." cm.
Lloyds A+C.P. Bon Shade deck 166'

M

RMA
24/5/11



© 2019

Lloyd's Register
Foundation

W 497-0341

RETAIN



© 2019

Lloyd's Register
Foundation

Do. of
Do. of
Do. of
Do. of
Do. above
Engine
Gross T
Less Cr
Less abo
Engine
FOUNDA
Less Eng
Less Na
Regis
as cut
LEN
Deck a
Dimens
FRAM
Do.
Do.
Spacing
"
"
REVE
Do.
FRAM
FLOO
"
"
"
"
FLOO
"
"
CENTE
"
"
"
SIDE C
"
"
MARG
"
"
"
INNER
"
"
BEAMS
"
"
BEAMS
"
"
BEAMS