

of Bilge pumps 1 Diameter of ditto $2\frac{3}{4}$ " Stroke 12" Can one be overhauled while the other is at work

S.S. "Abercraig"


hwc 40424
Lth no 10025

Before dealing with this case the Leith surgeons should be asked to state if, in view of the main boiler having been made in 1900, any deterioration has taken place in same & if it may now be taken as a new boiler & entered accordingly in the Register Book.

to R.H.
9/4/02

P.H.
9.4.02

R.S.
9.4.02



© 2019

Lloyd's Register

W498-0259

Material of stays H Diameter at smallest part $1\frac{7}{32}$ " Area supported by each stay 72" Working pressure by rules 236
Material S Thickness $1\frac{1}{16}$ " Pitch of stays $15 \times 14\frac{3}{4}$ " How are stays secured D.N + W. Working pressure by rules 236