

COPY.

Is Abercraig

Dundee Rpt No 6820

It is submitted that before this case receives the consideration of the Committee, the report and plans <sup>of midship section</sup> should be returned to the Surveyors and they should be informed that the number of strakes of plating on the sketch of midship section does not agree with the number as given on their report. They should therefore be requested either to amend the sketch of midship section or send a new section showing the plating as worked in the vessel. They should also amend the midship section as regards the thickness of floors in tank to correspond with their report.

They should be requested to state:-

1. Whether an intercostal plate has been fitted at the side keelson and attached to the shell as shown on approved sketch of midship section, but not mentioned on their report.
2. The weight of the stock of kedge anchor, and as the weight of this anchor ex stock exceeds 168 lbs., whether the anchor has been tested as required by the Act of Parliament (see footnote to Table 22).
3. The particulars of towline and hawsers other than those which they state are extra.



© 2019

Lloyd's Register  
Foundation

W498-0314