

*Port of* New York

August 13, 1926. 19

## REPORT ON MASTS, SPARS, AND RIGGING.

Dear Sirs:-

Having, in accordance with your instructions, examined  
the Masts, Spars, and Rigging, and Iron Work of same, of the  
S.S. *Munro* ex. S.S. "General G.W. Goethals"

have to report that I found The same in good condition with the  
following exceptions (after service was stripped)

Boom Port Side is slightly bent about two feet from Goose Neck.

Recommend-

3 Boom Port Side to be straightened.

*L*  
the Surveyors,  
Lloyd's Register of Shipping,

*Herbert W. Edgett*

© 2021

Lloyd's Register  
Foundation

W499-0151