

Beatsa

F.E.

Received by Chief Ship Surveyor 14/8/13

Received from Chief Ship Surveyor

VESSEL'S NAME St. J. Valgarth

Rpt. Mab

No. 8060

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.) - Extract from Sub-Committee's Report, 24/5/92.

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	50"	Proportions
Spar Sheerstrake . .		
Description of Framing:— deep built angle as approved. (viz., ordinary, deep, zed, channel or bulb-angle).		

RETAIN

The garboard strake is 1/20ths less in thickness than required by the Rules, but is compensated for by its increased width to give equivalent strength. In other respects the vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1 ("Steel") as recommended.

100A1. (Steel)
100A1 (etc) & deep framing
NB. Bulb DBa 90° u 64321/81 2885 FRT 356 APT/506
FK HBH Gen. Lloyds 4760 BH9 F26

M

14. 8. 13



© 2021

Lloyd's Register Foundation