

3m.2.25.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME SH S "AUDACITY"

Report Entk

No. 18476

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey 1st Entry

When due Rd Rule

✠ 100 A.1. (Steel) "Carrying petroleum in bulk"

1 dk (Stl). web frames.

D.T.f 11' 32t, F.P.T 36t, A.P.T. 29t.

FK, 8 B.H, pt asp, Cloyds A.C.P.

Q 64', F 26', "machy aft."



© 2019

26.11.25

Lloyd's Register Foundation

WS-0021

Bulb Angle, Plate, Tee Bulb, or Channel)

Tie Plates