

WS-0073

2m.10.39.

4 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Australind

Rpt.

Add.

No.

2386

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

REPAIRS TO ENGINES AND BOILERS DUE TO ~~DAMAGE THROUGH~~*wear & tear**Pat-downy boiler furnace worked at week adjacent to furnace.**now repaired by welding**2 new cylinder covers supplied - one fitted to No 6 cylinder*

*It is submitted that
this vessel is eligible to
remain as CLASSED. Subject to the Corer Cracking of
Auxiliary Compressor being removed at first opportunity.*

*Without other Special Condition**No 3 due 4.41**T.P. due 3.41*

© 2019

Lloyd's Register
Foundation