

Iron or Steel STEEL

State whether Classed by Lloyd's Register

Contemplated

WS-0081

Surveyors

Received from Chief Surveyors

ME Stl S M/V "AUSTRALIND" Report Slo No. 4909.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

ases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

ey 1^d Entry

When due

Revised Rule

100 A. I. (Steel) With Freeboard
D^c(Stl) + Shelter D^c(Stl) 3rd D^c(Stl) in N^o 1+3 holds + machinery space
ll D.B 346' 1009t, M.T. Ho' 1025t, F.P.T. 97t, A.P.T. 111t
K, 7 B.H (Coll B.H to Shelter D^c, 6 B.H to 2nd D^c) at Com, Lloyds ACP



1/2/2018
Lloyd's Register
Foundation