

Chief Ship Surveyor

Received from Chief Ship Surveyor

14 DEC 1920

65 5

NAME Steel D. S. "SONNENFELD" Rpt. Npt. No. 20035

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

Equipment

This vessel was classed 100A- in August last, no particulars of Anchors & Chain Cables being then available.

The Newport Surveyors now report having examined the Anchors, and forward particulars of markings found on same. No certificates for Anchors are available but they have been tested at approved machines in this country and the weights are as required by table 31, except that the stream anchor is slightly light, but the collective weight of the Anchors is in excess of that required.

The Chain Cables were ranged and compared with certificates. These Cables were tested as required by the Society, but the tests were carried out in Germany during the war by a former Surveyor to the Society, at a machine not approved by the Committee.

It is submitted the figure 1 might be assigned with the notation Lloyd's A.P.

100 A.1.

Lloyd's A.P.

J. M. AES
14.12.20



© 2020

Lloyd's Register
Foundation