

ballast tanks, also internal examination of double bottom.

MEMORANDUM.

I rang up Mr. Hunter, the Owners' Superintendent, who had enquired what work was still required to be done to complete the Special Survey No. 1, and was informed that he had proceeded to Cardiff, and that he would be in personal touch with the Surveyors at that port.



© 2020

8. 4. 20.

Lloyd's Register  
Foundation

WSE-0076

LR