

12 DEC. 1935

Undertaking Case

16 DEC 1935

Sent to Chief Surveyors 12. 12. 35

Received from Chief Surveyors

VESSEL'S NAME *54 Inverglass*

Report - No. -

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey *1st Special Survey No 2* When due *11.32*

Still laid up per Lloyd's Index
? General Examination

Southend

The 1st S.S.No.2 became due 11,32.

The ship being laid up the Owners have furnished the usual undertaking.

The case received consideration in December 1934, the Special Survey being then more than two years overdue, when no general examination was required.

According to Lloyd's Index the vessel is still laid up.

It is submitted for consideration whether in view of the Special Survey being now more than three years overdue the Owners should be asked to arrange for the ship to be generally examined.

W. G. R.

W. G. R.

13.12.35

S.



© 2021

Lloyd's Register
Foundation

W500-0131