

Undertaking Base

to Chief Surveyors 6. 12 34

Received from Chief Surveyors

7-DEC 1934

VESSEL'S NAME Sid G. Inverglass

Report

No. -

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ure of Survey / 1st Special Survey No 2 When due 11.32

Still laid up per Lloyd's Index

? General Examination

The 1st S.S. No.2 became due 11,32.

The ship being laid up the Owners have furnished the usual undertaking.

According to Lloyd's Daily Index the ship is still laid up.

It is submitted for consideration whether in view of the Special Survey being now more than 2 years overdue the Owners should be asked to arrange for the ship to be generally examined.

Handwritten signatures and initials:
W. G. S. 1934
M. G.
J. D.
J. J.
4.12.34

Last record of survey 7.30



© 2021

Lloyd's Register Foundation

W500-0132