

RT on the S.S. "Hgj."

It is concluded the bolts securing the portable plates at  
tops in Poop and Bridge Front Bulkheads of above vessel  
through the bulkhead plating, but the Surveyors should  
on this.

1/2 Bolt Pass here. bulkhead plating  
Su Minute Surveyors  
Letter 28/8/23

LH  
20.8.23

© 2020

Lloyd's Register  
W503-0141  
Foundation