

SPARE GEAR

One eccentric strap and sheave complete.

One dozen gauge glasses

Two dozens wallice rings for gauge glasses

One set of valves for the ballast pump

One bar of $\frac{1}{4}$ ", $\frac{3}{8}$ ", $\frac{5}{8}$ ", 1" round iron

Three plates of iron, assorted (1 cwt. each).

Six cylinder cover bolts

One main engine guide shoe

Six piston belts.

One set each of piston rings and springs for main engine

Twelve junk ring bolts and brass nuts.

One slide valve spindle with slide block complete for either engine

One pair crank pin brasses with liners.

One pair top end brasses with liners

One piston rod main engine

Two muntz metal studs with nuts for stern gland

One air pump rod with nuts complete

One circulating pump impeller and shaft

One set valve guards, springs and spindle for each auxiliary pump.

Half set main boiler check valves for main and auxiliary checks.

Two escape valves springs for feed pumps and one set feed pump valves and seats.

One spring for each size escape valve

One spare set of springs for main boiler safety valve.

One feed pump plunger, brass lined.

One bilge pump plunger

26 dozens belts and nuts, 4 $\frac{1}{2}$ condenser tube ferrules.

4 $\frac{1}{2}$ condenser tubes and 5 lbs. packing

Two belts and nuts for H.P., I.P. and L.P. piston and valve rod stuffing boxes.

105 assorted studs and nuts.

One set of bolts for guide shoes

One cast iron propeller

Two bottom end bolts and nuts.

Two top end bolts and nuts.

Two main bearing bolts and nuts

One set of coupling bolts and nuts

Two feed pump valves

Two bilge pump valves

Two cwt. iron plate

One cwt. of iron bars

One third crank shaft

One tail shaft with continuous liner with nut

35 feet. flexible hose 3" dia.

One set of air pump valves and quarter set of guards

One spare set of metallic packing rings for piston and valve rods.

Sheet steel templets of propeller cone and keyway supplied.

H.P. & I.P. piston rod gland and neck bushes for soft packing.

H.P. & I.P. valve rod gland and neck bushes for soft packing.

One spare disc for main engine stop valve.

One complete set of fire bars for each main boiler with patterns.

20 boiler tubes for main boiler

10 boiler tubes for donkey boiler

One set of check plates and one set of bridge plates for main boilers.

Four manhole dogs for main boilers

Two manhole doors stud bolts for main boilers.

TELEMOTOR SPARE GEAR

One spare gear box containing:-

Two bye-pass valve springs
 One bye-pass belt spring
 Two bye-pass valves
 Two red mica segments
 Two green mica segments
 Two flat gauge glasses
 Four S.E.A. rings and 8 headers (Rams)
 $\frac{1}{4}$ lbs header (bye-pass tappet rods)
 Two copper joints $1\frac{1}{4}$ " dia. (bye-pass plugs)
 Four $\frac{1}{4}$ " fibre joints (bye-pass flange)
 One fibre joints (bye-pass flange) (special)
 Two fibre joint special (tank door)
 Three fibre joint $\frac{1}{4}$ " dia. (pressure gauge valves)
 Two S.E.A. rings and 4 headers (" " ")
 Two copper pipes and two ruffs (pressure gauge pipes)
 One centring spring.
 One back pressure valve spring
 Four S.E.A. rings and 8 headers (Rams)
 Eight S.E.A. rings and 8 headers (charging valves)
 Two fibre joints $1\frac{1}{4}$ " dia. (charging valves)
 Two gauge glasses and cotton cord for same
 Two pipe couplings
 One wash out piece
 Ten copper ruffs and 18 copper joints for pipes
 (not in box)
 One 50 ft. length $7/16$ " bore copper pipe
 One glycerometer
 One Thermometer
 One spring.

CIRCULATING PUMP & ENGINE

One set pump bushes
 One set piston rings
 One piston valve
 One valve spindle
 One pair crosshead brasses and bolts
 One pair crankpin brasses and bolts
 One set main bearings brasses.

WEIR'S FEED PUMPS & HEATER

Two suction and two discharge seats complete, 7s & 6s, $1\frac{3}{4}$ "
 spindle cut valves, for $8" \times 10\frac{1}{2}" \times 21"$ pumps.
 Two suction and two discharge seats complete, 4s & 4s., $1\frac{3}{4}$ "
 spindle cut valves, for $5\frac{1}{2}" \times 7\frac{1}{2}" \times 15"$ pumps

EVAPORATOR

Twelve gauge glasses $\frac{1}{4}" \times 20\frac{1}{4}"$
 Two dozens glass rings $\frac{1}{8}"$

DYNAMO & ENGINE

12.5 K.W. generator:-

One piston rod complete w/- crosshead shoe and nut.
 One piston and ring
 One set connecting rod top end brasses bolts and nuts
 One set connecting rod bottom end brasses bolts & nuts
 One slide valve rod, with slide valve, eccentric rod
 and strap.

© 2020

LH

H

Lloyd's Register
Foundation

WS04-0080 25

Four carbon brushes
 Four brush holders
 One spare armature in box
 Four 5 K.W. generator
 One piston rod complete w/- crosshead shoe and nut
 One piston and ring
 One set connecting rod top end brasses bolts and nuts
 One set connecting rod bottom end brasses bolts and nuts
 One slide valve rod with slide valve, eccentric rod and strap.
 Two carbon brushes
 Two brush holders
 One spare armature in box

OIL BURNING INSTALLATION

One set nozzles for all burners
 One set diaphragms for all burners
 One case Thermometer
 One set valves for one pump
 One set strainer bags for suction strainers
 One set strainer bags for six delivery strainers

HOWDENS FORCED DRAUGHT

Nine right hand baffle plates
 Nine left hand baffle plates
 Three top baffle plates
 Six door baffle plates
 One piston ring
 Twelve mica plates.


 HOTEL

© 2020



Lloyd's Register
Foundation

WS04 - 0680 3/3

1921
18,26
12,13
10,11
Dec.1
24

letter
offers
o. of
safety
re their
malles

dated addressee
prob. look
about
for
to
descrip
appr
des13
siller
script
ates.

2020
Lloyd's Register
Foundation

you have sold because New Mexico has done so
when you buy oil from us we will give you miles to
travel over roads around the country

per Ry
Survey
Leave
F.R.I.
L.P.
X. D. C.L.

cipal
ent sha
n pipes
on off.
menis
ions
ed.

1 Id
no I
lid l
ning oil

cate o
ite qual
ssed
ook.

49 of

49 of

ed

1 Id
no I
lid l
ning oil

cate o
ite qual
ssed
ook.

49 of

49 of

ed

1 Id
no I
lid l
ning oil

cate o
ite qual
ssed
ook.

49 of

ed

1 Id
no I
lid l
ning oil

cate o
ite qual
ssed
ook.

49 of

ed

1 Id
no I
lid l
ning oil

cate o
ite qual
ssed
ook.

49 of

ed

1 Id
no I
lid l
ning oil

cate o
ite qual
ssed
ook.

49 of

ed

RETAIN

RELIABLE SURVEYOR

we are afraid we will not be able to do so
as we have not had time to go into
the details of your request, but we
will do our best to answer your
query in a timely manner. Please
allow us a few days to do so. Thank you for
your understanding.

Dates
Survey
while
building

ENE
tted
ickne

signed
omni
ssione
fri
for air true 9.22