

ed by Chief Ship Surveyor 31. 10. 17

Received from Chief Ship Surveyor

EL'S NAME Sing.S.S. "CARDIGAN".

Rpt. Mdb. No. 9925

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Survey

It is submitted before this case receives consideration, the Middlesborough Surveyors should be requested to state whether cargo battens are fitted in the shelter 'tween decks; also whether the stiffeners to the bulkhead on frame 150 are $11\frac{1}{2} \times 3\frac{1}{2} \times .60$ as shown on the plan.

They should also forward the approved sketch of the strengthening of the bottom forward.

L. Mat. 1/11/17.


31. 10. 17



© 2020

Lloyd's Register
Foundation

W505-0079

ES. 56
17
spaces
age 4
Ft.
399
Ship per Re
th 400.
FRA
or E
Double I
"
ies from c
to collision
ies from c
NAME, A
Double b
"
th of gird
and th
line for 3
f Engine
s at the e
3 the ha
xtended a
H Doub
f flanged
g of Soli
ER, in D
"
"
"
s at inter
b, numb
state i
.....
E, depth
and
to outsid
to floors
s at inter
of Brack
W PLA
of Mid
ness in
Re
or Shl
le, Plate
.....
eck, Sin
Bulbo
.....
hird &
gle, Pla
per edg
.....
ck, Ang
lb or C
.....
Angles on upper
.....
Spacing
BEAMS, Bridge Deck,

RETAIN



© 2020

Lloyd's Register
Foundation