

15 OCT 1936

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME

"CRISTOBAL COLON"

Rpt.

Gff.

No. 51616

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The 1st S.S.No.3, due 9,35, has been partly held.

The Cardiff Surveyors now report the vessel examined afloat and the Special Survey completed except as stated below.

The superstructures above the Shade Deck were found thin and rust drawn in places but efficient meantime. Owing to the unsettled state of Spain, no definite arrangements could be made as to where and when the necessary repairs will be carried out.

The Master stated these repairs would be dealt with at the first opportunity and in the Surveyors opinion this proposal merits the favourable consideration of the Committee.

The year of grace expired at the end of last month.


It is submitted action be deferred <sup>for a short time</sup> and the Bilbao

Surveyors advised.

Insert in S.R.L. 'Repairs to superstructures' etc

To complete the Special Survey - ~~See Report.~~

Repairs to Superstructures



© 2020

Lloyd's Register  
Foundation

W 506 - 00 86



