

BILBAO.

AUGUST 29th, 1923.

THOMAS MILLER

builders examined the twin screw steamer "CRISTOBAL COLON", 10,137 tons
of Barcelona on the 28th August, 1923 whilst lying in dry dock at
for the purpose of ascertaining the nature and extent of damage
to have been sustained by vessel fouling buoy in the Arsenal
on the morning of Sunday 26th August, 1923.

examination:-

FOUND

RECOMMENDED.

blade of starboard propeller with
fracture on leading edge and
fractured and bent in a length
seven inches by one and half inches
feet from tip on leading edge.

Starboard propeller to be
renewed.

on starboard rope guard broken.

To be renewed.

scored in way of starboard
rigger.

To be touched up.

The above recommendations were made so as to put the vessel
in good and efficient condition as before the accident.

Thomas Miller

see 250.00 pbs.



© 2020

Lloyd's Register
Foundation

W506-0099