

REPORT on the

*S. S. Cristobal Colon*

This submitted the Surveyor be informed that there does not appear to be any protection provided to the stairways through the upper deck in way of the open wells forward and aft, and any water which may enter through the openings in the vessel's sides would flow into the tween deck spaces below. The stairways should therefore be enclosed in substantial casings having hinged doors. Particulars of these casings should be submitted for approval.

*W.D.*



© 2020

Lloyd's Register  
Foundation

W506-0140