

REPORT OF TOTAL LOSS, CASUALTY, &c. 9062

No. 11437 in R. B. Wreck Book, p. 82/35

Date of writing this report 27th November, 1935

Vessel's Name *Steel S.S. Mackintosh* of *Bangkok* Tons { Net 28 Gross 97Built at *Hong Kong* When 1928 4 Casualty notice sent to Owner 19/9/1935 Owner's reply 1Owner's Name *Sriracha Co. Ltd.*Address *Bangkok, Siam.*Previously before
Committee. Date
Last Minute

Particulars of Classification.
+100A1 +LMC10,32
For Towing services
1234 BS1234
SS No1-32 TS10,33CL

SOURCE OF INFORMATION.

MACKINTOSH. — Bangkok, Sept. 16.—
It is reported that the Siamese tug
Mackintosh foundered off Kohsichang
during storm in night of Aug. 13
(? Sept. 13) with loss of two lives.

STORM AT KOHSICHANG, SIAM
Bangkok, Sept. 21.—The foundering off
Kohsichang during a storm in the night
of Aug. (? Sept.) 13 of the tug MACKIN-
TOSH has been confirmed. Considerable
damage was also done to the Sriracha
Company's pier at Sriracha, and five
Chinese lorches (wooden sailing lighters),
containing rice for shipment per vessels
loading at Kohsichang, were driven ashore
by the storm, resulting in heavy claims
for damaged rice.

Casualty 13/14th September, 1935.

Particulars of Casualty This vessel is reported to
have foundered off Kohsichang during
the night of 13/14th September in heavy
weather.

The usual casualty notice
was sent to the Owners on the 19th
September. No reply has yet been
received from them, but in a letter dated
the 25th September, the Bangkok
Surveyor confirms the above report, and
states that efforts to float the tug have
so far been unsuccessful.

sted Record

Date of Committee

Committee's Minute

Foundered 9.35.

FRI. 29 NOV 1935

Foundered 9.35.

© 2020

Lloyd's Register
Foundation