

11 JAN 1935 11

by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME

Tug. MACKINTOSH

Rpt. *Bgk*

No. *1023*

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/12.)

of Survey

Annual Survey.

The

Bangkok.

Surveyors report this vessel placed in

dry dock, bottom cleaned and coated, and ~~minor repairs effected.~~

It is submitted the vessel appears worthy to remain as
classified with record of survey *12-34* as recommended.

*100 A1
Towing Service
2-34 Bgk.*

J.D.

J.D.

11.1.35



© 2020

Lloyd's Register
Foundation

W506-0178