

BOARD REPORT on the

Lug "Mackintosh".


This Submitted new Cert. be sent to owners.

The Bangkok Surveyor should be informed that when freeboards are verified with a view to the issue of new certificates the particulars should be reported on a notification of marking form Rpt. 12, and not on Repair Rpt. form 8.

W.D.

22. 5. 29

© 2020



Lloyd's Register
Foundation

WS06-0101