

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Sc.K. "DAVANA". Report Liv. No. 112944**For the CHIEF SHIP SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/6/02.)

Nature of Survey _____

Condition

When due _____

Subject to framing in engine room found to be somewhat wasted beams and scored shell plating port & starboard sides being again specially examined at next dry docking about 11.39.

Note The Surveyors recommend the Special Survey be held when due



Lloyd's Register

WS09-0048 Foundation 19.8.39