

COPY.
PORT OF

9th August, 1939.

Dear Sir,

I have to acquaint you the Committee have had before them a report from the Society's Surveyor at Fleetwood on the steam trawler "DAVARA" in which he states that the frames in the engine room were heavily sealed and somewhat wasted. He further states that the shell plating from midships to aft, port and starboard, is getting wire chafed and indented. In the circumstances, he has recommended that these parts be specially examined at the next docking about November, 1939.


As regards the machinery the surveyor recommends that the stern bush should be rewooded at the same time as the above matters are dealt with.

I am, Dear Sir,

Yours faithfully,

Secretary to the
Liverpool Committee.

Sir George E. J. Moody,
GRIMSBY.



© 2021

Lloyd's Register
Foundation

W 509-0049