

For the information of Surveyors and the Committee only.

Received at

Office

JUN 18 1937

# Lloyd's Register of Shipping.

(Report on Vessel No. 95156 Port Newcastle)

## SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by Messrs. E. Jopling & Sons Ltd. <sup>Sunderland.</sup> for the Vessel SS. "Kilnwood" being <sup>REPAIR</sup> ~~built~~ by Messrs. J. Readhead & Sons Ltd. of South Shields have been inspected by me as set forth below and found to be, so far as can be seen, Sound.

This Casting has been despatched to Messrs. Donkin & Co. Ltd. Walkergate.

Lloyd's

No. 9484

Date 18.5.37

St. Galliford.

1-5.0" TILLER

Sunderland  
18.5.37


	STERN FRAME.	RUDDER FRAME.	STEM.
Inspected	/	Steel Casting	/
Standard Test Pieces.		Electric Furnace.	
Weight—		Heat treated	
Surface—		As per pattern	
Per cent. ...		Rough dressed.	
Impact Test—		18/5/1937.	
Time to fracture		TEST N <sup>o</sup> . 110	
Temperature ground ...		30.0	
Test—		30	
According to Rules and satisfactory ...		120°	
	8ft		
	Yes		

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

C. Q. LBS.  
H. 1. 20

of any chargeable) £ Twenty

to be paid at



© 2021

Lloyd's Register

on, state whether scrap or puddled iron. If of Steel, state whether made on the Open Hearth process.

igned MRS 6.37 William  
SM Cond.

W51-0121

