

6.

For the information of Surveyors and the Committee only.

Received at

Office

JUN 18 1937

Lloyd's Register of Shipping.

(Report on Vessel No. 95156 Port Newcastle)

No.

SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by Messrs. E. Gosling & Sons. Ltd. of Sunderland for the Vessel No. "KIRKWOOD", being ~~built~~ ^{REPAIR} by Messrs. John Readhead & Sons. Ltd. of South Shields have been inspected by me as set forth below and found to be, so far as can be seen, Sound.

This Casting has been despatched to Messrs. Donkin & Co. Ltd. Wallsend.

on Forgings or Castings.

Lloyd's
No. 9498
21.5.37

A. E. Galliford

Hand Gas Assayant. Sunderland 31.5.37.

	STERN FRAME.	RUDDER FRAME.	STEM.
Material* ...	/	Steel Casting	/
Made ...		Electric Furnace	
Heat treated ...		Heat treated	
Dimensions ...		As per pattern	
Process on Inspection ...		Rough dressed.	
When Inspected ...		21/5/1937.	
CASTINGS.		TEST N° 119.	
Tests on Standard Test Pieces.			
Tensile Test—		32.4	
Stress per square inch ...		25	
Elongation per cent. ...		120°	
Bending Test—		8 ft.	
Angle before fracture ...		ya.	
Impact Test—			
Height from ground ...			
Hardening Test—			
Made according to Rules ...			
and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

C. Q. LBS
5. 3. 27.

fee (if any chargeable) £ monthly etc.

To be paid at

of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

Committee's Minute

21.5.37 Wickham



© 2021

Lloyd's Register

W 51-0122