

3 E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SEL'S NAME "VENEZUELA". Rpt. Ams. No. 15215.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Part of Survey SPECIAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD FOR S.S. No. 1

~~LMC~~

LMC(M) due 4,37 , partly held 6,37, not advanced.

MS

BS.....due 2,38 , partly held 1,38, advanced.

~~now further advanced and the following repairs effected (due to~~

It is proposed to complete the survey <sup>in</sup> 5,38 (approved).

It is submitted that ~~this proposal merits approval and~~ the vessel is eligible to remain as classed, and WILL BE eligible for the record

MS 6,37 &amp; when the survey has been completed.

BS 1,38

The following remains to be done to complete the Survey

See reports.

*a limit to examine H. P. fluids exp. 438*



8.4.38. 2020

Lloyd's Register Foundation

WS10-0016



of Donkey Boilers  
Steam Pressure—  
Boilers

ey Boiler

Report  
culars

Surveys,  
Repairs,  
of Damage  
ing detail  
initials  
e cases v

his is  
amage re

veyor per

not done,

parts of th

special me  
r to assur

et date of

veyor ex

veyor ex

veyor ex

veyor ex

veyor ex

shaft no

now bee

shaft now

of examin

the parts

the Surv

insulation

vey is no

in bo

cam

own

form

or

rat C

is clearly

any al

ELMC

CS

on

Rem

2000



© 2020

Lloyd's Register  
Foundation