

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

3 Enclosures.

2nd June 1924.

Dear Sirs,

With reference to your First Entry Report No.11954 on the Steel Screw Steamer "PEGAWAY", I shall be glad if you will state whether you are correct in reporting the width of the upper deck stringer as 71", in view of the hatchways being increased in width from 26 feet to 27 feet; if this is the case it would appear that the ship has no tumble home, and the plans (which are returned herewith) should be corrected by you.

It is further concluded that the bridge deck half beams are fitted $7\frac{1}{2} \times 3 \times .42$ " bulb angle as approved, and not $9\frac{1}{2} \times 3 \times .42$ " bulb angle as reported, and that the hatches are strong and efficient, but I shall be glad to receive confirmation on these points.

The plans of midship section, profile and decks, and hatchways which are enclosed should be returned with your reply.

I am, Dear Sirs,
Yours faithfully,

The Surveyors,
MIDDLESBROUGH.

Secretary.

© 2020

LR

Lloyd's Register
Foundation

W51-0061