

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

4 JUN 1914

Date of writing Report 18 When handed in at Local Office 19 Port of London

No. in Reg. Book. Survey held at London Date, First Survey 25 May 1914 Last Survey 25 May 1914

on the Machinery of the Wood, Iron or Steel Ash Expellers for 391 Master YEAR MONTH

Tonnage Gross ☒ Net ☒ Vessel built at Belfast By whom Harland & Wolff When ☒

Registered ☒ Horse Power ☒ Engines made at (Donkey) By whom ☒ When ☒

No. of Main Boilers ☒ Boilers, when made (Main) ☒ Owners ☒ Port ☒ Voyage ☒

No. of Donkey Boilers ☒ If Surveyed Afloat or in Dry Dock ☒ (State name of Dock.)

Steam Pressure in Main Boilers ☒ Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Donkey Boilers ☒

Last Report No. Port

Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers?

and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

and of the Donkey Boiler?

Has screw shaft now been drawn and examined?

Is it fitted with continuous liner?

or two liners?

or is it without liners?

Has shaft now been changed?

If so, state reasons

Is the shaft now fitted new?

Has it a continuous liner?

or two liners?

or is it without liners?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

At Mr. J. Stone & Co. Deptford examined four (4)

Ash Expellers for above vessel.

Numbered 207 - 208 - 209 - 210.

Examined & found satisfactory

Expeller No 207 examined under working conditions & found & work satisfactory.

Hoppers, buckets, Glinders & T. Pucis Stamped JRB

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, R.S. 9,11, B.&M.S. 9,11, or L.M.C. 9,11 140 lb., E.D., &c.)

The above submitted for the Committee's information.

Survey Fee (per Section 28) £ : : Fees applied for 19


Special Damage or Repair Fee (if any) (per Section 28.) £ : : Received by me, 19

Travelling Expenses (if chargeable) £ : :

Thomas R. Blackie
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

Assigned



© 2020

Lloyd's Register Foundation

To amount 1st Survey

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

17/2/10

17/2/10

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020
Lloyd's Register
Foundation