

Chief Surveyors

5. 7. 34

Received from Chief Surveyors

VESSEL'S NAME

M. L. S. "MELITA"

Report

pls.

No.

54697.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

2nd

No.

1

SURVEY PARTLY HELD. +

Damage

When due

1. 34

When proposed to be completed


*before again going into commission
Vessel to be laid up.*

Position of Survey held, &c.

To complete the Survey:- See Report.

*Subject to the stern frame repaired by E. W 1.23, 11.23 + 1.30
Being specially examined at next dry docking.*

*A shell plate on starboard side to be permanently repaired
at completion of the Special Survey.*



WS'13-0125

2020
8/5.7.34

Lloyd's Register
Foundation