

Surveyors _____

Received from Chief Surveyors _____

NAME *Std S. MELITA*

Report *Lls*

No. *44398*

For the CHIEF SHIP SURVEYOR AND CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Drydocking & fitting of additional strengthening
to superstructures *When due*

Subject:-

Indented plating on port side forward. being dealt with at Owner's convenience when frame (E.W. repairs 1911. 1913) being specially examined at next drydocking

WS'13-0142



© 2020

Wm. L. & Co.
Lloyd's Register
Foundation