

Chief Surveyors

Received from Chief Surveyors

SHIP NAME

Clan Mackenzie

Report Lw

No. 110556

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Survey

Damage

When due

-


Damaged by collision + stranding 10.37.

Vessel now being broken up. Recommendation
transmitted that class be withdrawn.

Dubb

Wk Rpx 9433

The Certificate of Classification is
endorsed "Cargo battens not
fitted" and the same notation is to
be entered in the Register Book



Lloyd's Register
Foundation

1100-515-0011