

by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

11 SEP 1936

L'S NAME \_\_\_\_\_

"CAMPEADOR"

Rpt. \_\_\_\_\_

Bcl. \_\_\_\_\_

No. 4400

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

of Survey \_\_\_\_\_

The Barcelona Surveyor reports the vessel placed in dry dock and the requirements of the 1st S.S.No.1, due 7,36, partly complied with and minor repairs effected.

It is stated that the Survey will be completed at the first convenient opportunity on the return of more settled conditions in Spain.

It is submitted action be deferred.



© 2019

Lloyd's Register  
Foundation

Ws'16-0003