

5 E

2 JUN 1937

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

L'S NAME

"SANDGATE CASTLE".

Rpt.

Hul.

No. 47850.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey

~~DEFECTS~~-WEAR AND TEAR.

DOCKING.

Wear and tear repairs.H.P. turbine casings, ^{repaired} and some steam pipes renewed.

It is submitted the vessel is eligible to remain as classed without
 Record of Survey as recommended.

LR

© 2019

 Lloyd's Register
 Foundation
 31.5.37.

WS16-0186