

S.S. "SANDCATE CASTLE".

IT IS SUBMITTED the Owners' Superintendent be informed that as requested in the phone message received on the 19th instant, ~~a search has been made for other cases in which settling tanks are situated immediately above boilers.~~

~~There is, however, no special ^{index} ~~notice~~ of such arrangements to enable the vessels to be traced, and the only result of the search is that~~ somewhat similar arrangements are to be found on a number of recently constructed motor vessels, in which the donkey boilers are situated immediately below tween deck oil fuel bunkers.

The arrangements were approved by this Society and ~~the~~ ^{so far} have given satisfaction.

Hand. 47850

23rd July, 1938.



© 2019

Lloyd's Register
Foundation

WS16-0226